



IECEX Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.: **GB/SIR/QAR07.0033/08** Page 1 of 1

QAR Free Ref. No.: **80009129** Status: **Issued**

Details of change: 2019 Recertification Audit Date of issue: **2019-12-03**

Site(s) audited: **Rotork Fluid Systems** Valid until: **2022-08-16**
(A Division of Rotork UK Ltd.)
9 Brown Lane West
Holbeck
Leeds LS12 6BH
England
United Kingdom
Audit date: **2019-10-26**

Issuing ExCB: **SIR - SIRA Certification Service**

Manufacturer: **Rotork Fluid Systems**
(a Division of Rotork UK Limited)
9 Brown Lane West
Holbeck
Leeds
LS12 6BH

Location of Manufacturer: **United Kingdom**

Product information: Actuators and hydraulic power units

Protection concept: **Ex d, e, m**

Related QARs:

GB/SIR/QAR07.0033/00	GB/SIR/QAR07.0033/01	GB/SIR/QAR07.0033/02
GB/SIR/QAR07.0033/03	GB/SIR/QAR07.0033/04	GB/SIR/QAR07.0033/05
GB/SIR/QAR07.0033/06	GB/SIR/QAR07.0033/07	

Related Certificates (manual insertion): **IEEX SIR 05.0051X**
IECEX SIR 05.0052X

Related Certificates (automatic linking):

Related Certificates for previous versions:

IECEX SIR 11.0041X issue: 0	IECEX SIR 11.0041X issue: 1	IECEX SIR 11.0041X issue: 2
IECEX SIR 11.0041X issue: 3	IECEX SIR 11.0041X issue: 4	IECEX SIR 11.0041X issue: 5
IECEX SIR 15.0046X issue: 0	IECEX SIR 15.0046X issue: 1	IECEX SIR 15.0046X issue: 2
IECEX SIR 15.0046X issue: 3	IECEX SIR 15.0046X issue: 4	IECEX SIR 16.0095X issue: 0
IECEX SIR 17.0033X issue: 0	IECEX SIR 17.0033X issue: 1	IECEX SIR 17.0033X issue: 2
IECEX SIR 17.0045X issue: 0	IECEX SIR 17.0045X issue: 1	IECEX SIR 17.0045X issue: 2
IECEX SIR 17.0046X issue: 0	IECEX SIR 17.0046X issue: 1	

Comments: